SE Tylose Louisiana, LLC Quality Assurance 26270 Hwy. 405 (River Road South) Plaquemine, LA 70764-6816 Tel. 225.309.0110





Inspection certificate - Certificate of Analysis according to EN 10204-3.1

Date: 22.05.2020

Page: 1 / 1

Your order from 17.04.2020

Order No.

: 0001-00037605

Delivery no./Pos.

: 80246872 / 900004

Order

: 154353

Material

: TYLOSE HS 100000 YP2

Material-no. Batch No.

: 20422625128

: USAT208046

Quantity

: 5.625

On the batch, of which the consignment is a part, the following values were determined. They conform to the agreed product specification.

Inspection characteristic/-method	Specification	Result
Date of manufacture	100.00	19.03.2020
Recommended re-evaluation date		19.03.2022
Moisture (as packed)	<== 6,0	3,5 %
Sulphated Ash	<= 6,0	3,6 %
pH-Value (1.0 %)	5,5 - 8,0	6,4 NoDim
Particle Size <0.180 mm (80 mesh)	>= 85,0	98,4 %
Viscosity Brookf. LV - 25°C - 1.0 %	3800 - 5000	3950 mPa·s

These results refer to the date of manufacture and shall merely show the conformity of the batch delivered with the specifications currently determined for this product. The indication of the data and the recommended re-evaluation date should not be construed as guaranteeing the consistence or permanency of the product or specific properties of the product or its suitability for a particular application. The above particulars do not release the customer from the obligation to carry out an inspection of goods received.

Wade Wittig (inspection representative) This report is not to be signed.