

SE Tylose Louisiana, LLC
Quality Assurance
26270 Hwy. 405 (River Road South)
Plaquemine, LA 70764-6816
Tel. 225.309.0110

ShinEtsu

Amichem S.R.L
C.U.I.T: 30-70865314-0
Parque Industrial Metropolitano
Avenida Eva Perón (ex Las Palmeras)
2121 PÉREZ, SANTA FE
ARGENTINA

ORIGINAL

Inspection certificate - Certificate of Analysis
according to EN 10204-3.1

Date: 17.02.2025
Page: 1 / 1

Your order from 22.01.2025
Order No. : 0001-00041230
Delivery no./Pos. : 80322551 / 900002
Order : 203776
Material : TYLOSE HS 100000 YP2
Material-no. : 20422625128
Batch No. : USAT250014
Quantity : 3.375 KG

On the batch, of which the consignment is a part, the following values were determined. They conform to the agreed product specification.

| Inspection characteristic/-method | Specification | Result |
|--------------------------------------|---------------|------------|
| Date of manufacture | | 05.01.2025 |
| Recommended re-evaluation date | | 05.01.2027 |
| Moisture (as packed) | $\leq 6,0$ | 1,8 % |
| Sulphated Ash | $\leq 6,0$ | 4,2 % |
| pH-Value (1.0 %) | 5,5 - 8,0 | 7,0 NoDim |
| Particle Size < 0.180 mm (80 mesh) | $\geq 85,0$ | 99,0 % |
| Viscosity Brookf. LV - 25°C - 1.0 % | 3800 - 5000 | 4400 mPa.s |

These results refer to the date of manufacture and shall merely show the conformity of the batch delivered with the specifications currently determined for this product. The indication of the data and the recommended re-evaluation date should not be construed as guaranteeing the consistence or permanency of the product or specific properties of the product or its suitability for a particular application. The above particulars do not release the customer from the obligation to carry out an inspection of goods received.

Shawn Streacker (inspection representative)
This report is not to be signed.